Toledo Express Airport 10971 E. Airport Services Rd. Swanton, Ohio 43558 419-865-2311 Fax: 419-866-8322 • Turbine Fax: 419-866-1807 • Airframe Fax: 419-866-4224

COMMERCIAL INVOICE / REPAIR ORDER INSTRUCTIONS

The following items are required information on your commercial invoice:

- 1. SHIPPER NAME, ADDRESS AND CONTACT INFORMATION
- CONSIGNED TO NAME, ADDRESS AND CONTACT INFORMATION
- 3. DESCRIPTION OF ITEM(S) TO INCLUDE
 - a. MODEL NUMBER
 - b. PART NUMBER
 - c. ITEM NAME / NOMECLATURE
 - d. SERIAL NUMBER (IF APPLICABLE)
 - e. QUANTITY OF ITEM
 - f. VALUE OF ITEM
 - g. COUNTRY OF MANUFACTURE OR ORIGIN
 - h. HTS NUMBER
 - i. 9801.10.1012 is US Mfg Goods returning for repair & re-export
 - ii. 8411.21.4010 Turbopropeller engine, less than 1100kW, for use in Civil aircraft
 - i. TYPE OF EXPORT (TEMPORARY)
 - j. REASON FOR EXPORT (RETURN TO COUNTRY OF ORIGIN & REPAIR.)

 ITEM TO BE RE-EXPORTED AFTER REPAIR.)
 - k. WORK TO BE ACCOMPLISHED (FOR REPAIR ORDER)
 - I. SPECIAL REQUESTS (IF ANY).
 - *i.* MILITARY ENGINES (All T76 engines, TPE331-1-101F, TPE331-1-151A, TPE331-12B-701A, TPE331-12B-702A, TPE331-12B-703A)
 - 1. HTS number is 8411.21.4050 Turbopropeller engine, less than 1100kW, NOT for use in civil aircraft
 - 2. ECCN 9A619.a
 - 3. License exception RPL.
 - ii. Large Block (-14 or -15 engines)
 - 1. HTS is 8411.22.4010 Turbopropeller engine, less than 1100kW, for use in Civil aircraft
 - 2. HTS is 8411.22.4050 Turbopropeller engine, less than 1100kW, NOT for use in Civil aircraft

^{*}Responses noted in parentheses & in italics are what should be noted.



Toledo Express Airport 10971 E. Airport Services Rd. Swanton, Ohio 43558 419-865-2311 Fax: 419-866-8322 • Turbine Fax: 419-866-1807 • Airframe Fax: 419-866-4224

PLEASE NOTE: Per current US Customs regulations, it is the responsibility of the shipper to provide correct information and paperwork, including Harmonized Tariff Schedule (HTS#), Foreign Shipper's Declaration & Importer's Declaration (to be completed by National Flight).

If the freight company (FedEx, UPS, DHL) has to research & obtain the information for an item left blank and the data they submit is the wrong code/ item/ etc, they freight company is NOT LIABLE for the US duties / taxes assessed due to the error. To correct a US Entry error, there is a minimum 75.00 re-filing fee with US Customs if the data was not provided on the Commercial or Proforma invoice or Declarations paperwork. Any US duties or taxes assessed to National Flight on import shipments will be billed to the shipper / owner of the goods.

Please reference U.S Regulation 19 CFR 10 SUBPART A for general provisions. If you are subject to a Free Trade Agreement, please refer to SUBPART A as well as your specific SUBPART.

^{*}Responses noted in parentheses & in italics are what should be noted.

ABC Corporation

123 Main Street

Hounslow, Middlesex, TW6 2GW, United Kingdom

Consigned To:

National Flight Services, Inc.

10971 E. Airport Service Road

Swanton, OH 43558 USA

Description:

MODEL

TPE331-5-252C

P/N

3103860-1

DESCRIPTION

TURBO-PROP ENGINE

SERIAL NUMBER

P-22300

MANUFACTURER

MADE IN U.S.A.

HTS#

9801.10.1012 U.S Goods returned for repair

8411.21.4010 Turbopropeller Engine, not exceeding 1,100 kW, for use in civil aircraft

Reason for Export: Enclosed items (s) is/are being returned for repair.

Made in the United States, not advanced or improved abroad.

Manufacturer's Name & address: Honeywell Aerospace

1944 E. Sky Harbor Circle Phoenix, Arizona 85034

I declare that the above information is true and correct to the best of my knowledge and that the goods are of the origin specified above.

ABC Corporation Joe Green Shipping Manager

ABC Corporation

123 Main Street

Hounslow, Middlesex, TW6 2GW, United Kingdom

Consigned To:

National Flight Services, Inc.

10971 E. Airport Service Road

Swanton, OH 43558 USA

Description:

P/N

394408-8-1

DESCRIPTION

FUEL FLOW DIVIDER

SERIAL NUMBER

P-4354C

MANUFACTURER

MADE IN U.S.A.

HTS#

9801.10.1012 U.S Goods returned for repair

8411.91.7010 Turbopropeller Aircraft part, for use

in civil aircraft

Reason for Export: Enclosed items (s) is/are being returned for repair.

Made in the United States, not advanced or improved abroad.

Manufacturer's Name & address: Honeywell Aerospace

1944 E. Sky Harbor Circle Phoenix, Arizona 85034

I declare that the above information is true and correct to the best of my knowledge and that the goods are of the origin specified above.

ABC Corporation Joe Green Shipping Manager